

Sequence care symbols

washing - bleaching - drying - ironing - professional cleaning :



Care symbols

Washing



hand wash



max. 40°C



max. 60°C gentle process



max. 30°C



max. 40°C gentle process



max. 95°C



max. 30°C gentle process



max. 40°C very gentle process



do not wash



max. 30°C very gentle process



max. 60°C

Bleaching



any bleach allowed



only oxygen/non-chlorine
bleach allowed



do not bleach

Drying



tumble drying possible
drying at lower temperature



tumble drying possible
normal temperature



do not tumble dry

Ironing



max. 110°C



max. 150°C



max. 200°C



do not iron

Professional dry-cleaning



professional dry-cleaning
normal process



professional dry-cleaning
gentle process



do not dry-clean